bowman
TRAILER LEASING

C29245
RA0028038

Inbound Inspection

Customer: DOUBLE R TRANSPORT

UNIT: 601341

VIN:

License:

YEAR:

ROAD/STORAGE

MAKE:

MODEL:

Destination: DALLAS

62 TW= 25 37

Damage Identification Symbols

B= Bent/Broken C=Cut M=Missing T=Torn H=Hole S=Scrape

All new damage and deficiencies versus outbound inspection noted below



Pos	Brand	PS	Pos	Brand	Depth	PS
LOF		6	ROF			4
LIF		4	RIF			5
LOR		4	ROR			4
LIR		7	RIR			3
Tire Size			Disc/spoke			
Hubodometer in:	NO HUB		DOT		CAN'T READ	
Brakes F/A			Brakes R/A			
Registration Current YES/ NO			Exp Date			

TECH	BILLABLE	REPAIRS TO BE PERFORMED	LABOR HOURS	MATERIALS COSTS
		LEFT RADIUS DAMAGE		
		BENT ICC		
		MUD FLAP BRACKET BENT		
		RIGHT DOOR SEAL DAMAGE		
		DAMAGED SCUFFLINER		

TECH	BILLABLE	MATERIALS	QUANITY	MATERIALS COSTS

INSPECTOR: L. JORDAN

DATE: 8/11/2020

DRIVER SIGN/PRINT: L. Jordan, Double R

Vendor/ Mechanic: SHERRY

Completed Date: