

Record of Annual Inspection

The Inspector of this vehicle meets the qualification requirements contracted in D.O.T. rule 49 CFR section 396.19

102	33 Governor Lane Bl	Vol
P.O. Box 433 Williamspor P - (800) 635-6733		rt, MD 21795-0733 Inspection Location: Creensborn V.C.
P - (800) 635-6733		rt, MD 21795-0733 "Spection Location: (reenstrong
F - (301) 223-7674		(Branch ID, City & State)
. ,	301/223-76/4	Unit #: 140743
		Unit #: 140743 MFG/Year (20 one 0) Serial #: 16 244062315000452 Date of Inspection: 8-17-20
OK	DEFECT N/A	Date of Inspection: 8-17-20
1	19/13	(Month / Day / Year)
	u ()	Registration will be a second
[}	0 n	Registration valid installed in Registration Holder. License Plate # (155) 920 State Expiration: Conspiculty Tape sides, rear ICC Assembly
		Conspiculty Tane sides and State 1 Expiration:
Ð-	0 0	TOUR ICC ASSEMBLY and
F1-		All Marker, Clearance, Stop/Turn, Flashers and License Plate Lights are operational. All Electric
B	0 0	Harnesses are secured properly. Seven way plug properly secured. All Front and side panels are five to the secured.
	935 1 4	All Front and side panels are from the
B	[] []	Rails are free of damage, properly fastened to cross members, posts and panels. ICC assembly is properly secured, step is a secured step
		rec assembly is proportion.
		Taillights are functional and functional and have
9	0 0	
		Air Ride Suspension Spring Ride Suspension Springs, Rebound holts U. Bolte Suspension
		Springs, Rebound bolts, U-Bolts, Equalizers, Radius Rods, are free of damage, excessive wear, Leaks, brackets are attached and
rı		Secure and free of defects. Air bags are intact, shocks are properly installed, free of excessive wear, Leaks, brackets are attached and secure. Slider Ralls are are attached.
F)	0 0	The street and series are series and series and series and series and series and series
	-	
		Slider Rails are properly secured to the cross members, no gaps or broken welds. Slider Pins are properly Gear straight, braces intact, properly attached to Wing Plate and Cross Members handle in good. Landing and able to be properly secured.
9	0 0	and able to be properly secured. OEM Gussets are intact. Landing
		Gear straight, braces intact, properly attached to Wing Plate and Cross Members handle in good condition All Glad Hand Grommets and Services of the Services
		All Glad Hand Grommets are free of tears and excessive wear. Glad hands are properly secured to the front And defects. Air tanks are properly secured and return spring. All airlines are free of wear manifesting.
4	o n	Panel/bulkhead; Airlines are secured by a slider return spring. All airlines are free of wear marks, chaffing Brake adjustment the secured and drained.
<u>u [] []</u>		Brake adjustment charles and drained.
		Brake adjustment checked, brake thickness measured, slack adjusters properly secured and operational. Corrosion. Brake Drums are intact, no excess wear or damage, free of oil and grease.
		Corrosion. Brake Drums are intact, no excess were not caged, are free of excessive
		Corrosion. Brake Drums are intact, no excess wear or damage, free of oil and grease. Front axie brake thickness
0 1	7 69	Rear Axle Brake Thickness
rı f] []-	Optional equipment is
		And in good condition
Q r) ()	Optional equipment is functional (Lift Gate), batteries secured properly. Winches & straps properly secured
	[]	Tires matched (with a comments
		All lug nuts properly secured, rims are free of creeks o
TREAD DE	TI 1 22 /	All lug nuts properly secured, rims are free of cracks, damage, or excessive wear with no oil present on rims. Pagint
POSITION	TH 32/NDS"	Radial = R Radial Posses
LFO	TREAD DEPTH	IRS BOOK RECEIPTION OF THE PROPERTY OF THE PRO
LFI	-10	INCO PEO INCAD DEPTH LBS
LRO		RFI 100
LRI	-	RRO
-25,75		RRI
UBOMET	FR	
	-11	Tire Size
SPECTED BY	,.	RIM TYPE
PRINT NAME		
	MAINE	Vans Disw
CATION: THIS VEHICLE HAS BEEN		SIGNATURE